# HP 7 1800 Audio Jack Replacement

This guide will help you replace the audio jack in your HP 7 1800.

Written By: Trevor Shumate

INTRODUCTION

You will be disassembling the HP 7 1800 and using a soldering iron to replace the audio jack.

🔧 TOOLS:

- Spudger (1)
- Portable Soldering Iron (1)
- Tweezers (1)

This document was generated on 2020-11-20 08:22:21 PM (MST).

Step 1 — Remove the back panel

- Use a Spudger to open the back panel. Be careful not to break the tabs.

Step 2 — Desoldering the audio jack

- Desolder the top lead for the six solder points.

www.iFixit.com

Step 3 — Removing the audio jack

- Once the solder is removed, gently pull the audio jack away from the motherboard with tweezers.

To reassemble your device, follow these instructions in reverse order.