




# HP Pavilion x360 11-p110nr Hard Drive Replacement

If your HP Pavilion x360 11-p110nr laptop has a faulty Hard Drive, this guide will take you step-by-step in removing and replacing the original hard drive.

Written By: Alvin Muttayi




This document was generated on 2019-09-18 08:45:24 AM (MST).

 **TOOLS:**


- [Phillips #0 Screwdriver](#) (1)

## Step 1 — Hard Drive




- Make sure the laptop is turned off, and the power cable is removed.
- ⚠ Leaving the laptop turned on can cause damage to the hardware and any stored data.

## Step 2



- Turn the laptop over to access the backside of the computer.
- Identify and confirm that the laptop is an HP Pavilion DV5T-1000.
- In order to remove the hard drive compartment cover, first remove the screws located on the panel, using a size 0 Phillips head screwdriver.

### Step 3



- Remove the 4 screws using a size 0 Phillips head screwdriver.
- Pull the hard drive up and out, to remove it from the compartment to replace it.

To reassemble your device, follow these instructions in reverse order.