



CTS squeaky seat fix

This is a fix for the common problem of a squeaky seat in the gen 2 CTS

Written By: Dan Dunham



INTRODUCTION

This will show how to pull the seat back off and fix the constant squeak that often develops in these seats.

Step 1 — CTS squeaky seat fix



- Check out this short video that will run through the basics of removing the back of the seat, and finding and fixing the source of the squeak these seats often develop.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2019-08-19 04:05:11 PM.