



Microsoft Surface Pro 7 Screen Replacement

Screen replacement for Microsoft surface pro 7 How to do screen repair

Written By: Mark D Schlossman





PARTS:


- [Surface Pro 7 Screen](#) (1)
-

Step 1 — Screen



- Cracked Screen Surface Pro 7

Step 2



⚠ Apply lots of heat to get screen off!

- Pry with splicer and suction cup to get plastic guitar pick in.

Step 3




- Open screen from the top down++

⚠ We need to disconnect the battery


- When screen is tilted upwards its easier to get to the battery before disconnecting the display cables
- Remove battery connect by pushing on the edges
- Wiggle each edge of the plastic cable cover to get it out with out. Make sure you don't force it out.

Step 4



- Display Connections
- Battery Connections

Step 5



- Remove from old screen to the new

Step 6



- Test device before putting adhesive down
- Test wifi, bluetooth and screen of course

To reassemble your device, follow these instructions in reverse order.