




iMac Intel 21.5" EMC 2544 Fan Replacement

Prerequisite to remove the fan after the hard drive brackets.

Written By: Sam Goldheart




INTRODUCTION

Prerequisite to remove the fan after the hard drive brackets.

TOOLS:


- [T10 Torx Screwdriver](#) (1)
-

Step 1 — Fan



- Gently pull the fan cable connector straight away from its socket on the logic board.

Step 2



- Remove the three 12.3 mm T10 shoulder screws securing the fan to the rear enclosure.

Step 3



- Remove the fan from the iMac.

To reassemble your device, follow these instructions in reverse order.