



Repairing a Panasonic SA-HT810V with the H02/H07 error

Written By: Nathan Cheadle



INTRODUCTION

This guide describes how to fix the H02/H07 error that is common with Panasonic DVD/VCR players.

TOOLS:

- [Phillips #2 Screwdriver](#) (1)
 - [Lubricant](#) (1)
-

Step 1 — Repairing a Panasonic SA-HT810V with the H02/H07 error



- With the front display of the device facing you, rotate the device 90 degrees counter clockwise.
- Remove the screw that is on the right side of the panel facing you.
- Now rotate the device 180 degrees and remove the second screw.
 - Remove all screws with a phillips head screwdriver.

Step 2




- Rotate the device so that the back faces you.
- With a phillips head screwdriver, locate and remove the two screws highlighted by the red circles in image one.

Step 3



- Before removing top cover make sure that the back of the device is facing you.
- Remove the top cover by bending out on the sides, and pulling the cover towards you while applying upward pressure.

Step 4



- i** Note that the spindle you will be lubing is located underneath the white disk device highlighted in figure one
- Tilt the device on its front side until you can see underneath the white circular component mentioned in the note above.
 - Locate the spindle circled in figure two and apply one or two drops of 3 in 1 lubricating oil to the spindle.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2019-07-17 02:21:14 PM.