




Dell Optiplex 760

Escrito por: Jesus Salgado



INTRODUCCIÓN

Cuando el Pc no arranca : Reparar y lubricar ventiladores.

Paso 1 — Dell Optiplex 760



- Remove the rear sticker from the fan.
- Remove the black clip that holds the shaft and washer.

Paso 2 — Bearings



- Remove bearings and blades
- Beware of the remaining pieces as they have order and are very small.

Paso 3 — Lubricate



- Insert the CRC electrode 2-26 electrode and spray carefully.
- Place the bearings and repeat the process

Paso 4 — Assembling blades



- First we set up the dock.
- Washer
- And bearing.

Paso 5 — Mount



- We attach the blades
- We close the clips. Ready.

Seguir las instrucciones y nunca mojar las bobinas de cobre.