



# LG VX5500 Audio Port Replacement

This guide will provide the necessary steps to replace the audio port.

Written By: Kurt Beske



---

## INTRODUCTION

If no sound comes from headphones that are plugged into the audio port, you may need to install a new one. Follow this guide to diagnose and resolve the issue.

---

### TOOLS:

- [Phillips #00 Screwdriver](#) (1)
  - [iFixit Opening Tools](#) (1)
  - [Soldering Workstation](#) (1)
  - [Tweezers](#) (1)
-

## Step 1 — Battery



- Remove the battery cover by placing your thumb on the small ridge near the top of the phone back and push downward, exposing the battery.
- ⓘ Our device did not come with a battery cover so it is not shown here.
- Remove the battery using your finger to pry it out of the battery housing.

## Step 2 — Audio Port



- Remove the (2) rubber screw covers located near the hinge of the phone using tweezers or a thumb tack.
- Unscrew the (4) 3.6mm screws using a #00 Phillip's head screw driver.

## Step 3



- Carefully pry off the phone's backing using a plastic opening tool.
- Slip the tool into the crack between the keypad (front panel) and the back panel.
- Slide the tool along the sides of the phone to detach the tabs holding the backing on.

## Step 4



- Locate the audio port; this is what it should look like.
- The audio port is mounted and connected at 6 points. Check the integrity of these connections.
- ⓘ If any of the connections are dislodged or the audio port is damaged, desolder the port and install a new one.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2019-07-15 03:23:46 PM.