



Swimming pool Pump strainer housing cover o-ring Replacement

Pool pump strainer o-ring

Written By: tcagle53



INTRODUCTION

This guide will pictorially show you how to detect an age failed pump strainer cover o-ring. Replacing actual o-ring is very trivial so that won't be shown.

Step 1 — Bubbles apparent in strainer chamber



- Bubbles visible in strainer chamber (or at outlet jets)? Bend oring at extreme angle as shown. If tiny fissures are apparent as in photo a new o-ring will solve the issue.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2019-04-17 01:31:51 AM.