



Gasket in the inlet valve

Replacing the gaskets (seals) at the inlet valve of the Saeco Minuto coffee machine.

Written By: VauWeh



INTRODUCTION

The seals of the inlet valve are under a lot of strain and need to be replaced from time to time. The replacement is easy. This will show you how to do this.

TOOLS:

- [T10 Torx Screwdriver](#) (1)
- [Metal Spudger](#) (1)

PARTS:

- [New Item](#) (2)

Step 1 — Gasket in the inlet valve




- Open the side panel and remove the brewing unit.

Step 2



- Remove the drip tray underneath the brewing unit.

Step 3



- Unscrew the four Torx T10 screws that hold in place the cover of the inlet valve.
- Remove the cover.
- Clean well the inside and back panel of this cover.

Step 4



- Replace the gaskets using a blunt tool, such as a spatula.
- ⓘ The upper gasket is larger.
- Smear the gaskets with silicone grease.

Work through the steps in reverse order to re-assemble your device.