



Turtle Beach Ear Force Stealth 500P Headband Pad Replacement

A guide for replacing the headband pad on Turtle Beach Ear Force Stealth 500P headphones.

Written By: Noah Franklin



INTRODUCTION

In order to complete this repair, you will need to order a replacement headband to replace the defective part.

TOOLS:

- [Metal Spudger](#) (1)
-

Step 1 — Headband Pad




- Grab one end of the headband pad and pull up slightly, exposing where it is glued to the backing.

Step 2



- Using a thin tool carefully scrape away the glue underneath the band while pulling the pad up, careful not to rip it.

Step 3



- Once the pad has been completely removed, scrape off any remaining residue.

Step 4



- Follow the directions of the replacement pad on how to attach it to the headband.

To reassemble your device, follow these instructions in reverse order.