



3rd Party Battery Installation Trick for Misshapen A1181 Batteries

In this video I demonstrate how to modify a misshapen A1181 3rd party battery slightly to allow for a perfect installation.

Written By: rdklinc



INTRODUCTION

3rd party (non-OEM) A1181 batteries are often slightly misshapen, making them difficult to install and lock into the battery compartment. In this video I demonstrate how to use a razor blade to modify the battery slightly to allow for a perfect installation.

TOOLS:

- [Precision Utility Knife](#) (1)
-

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2019-07-08 08:00:44 PM.